

1/44




FIG. 1

202290" TFS500T

2/44




FIG. 2

20/2290" T.555500T




FIG. 3

202290" TFS9500T

4/44




FIG. 4

20/2290" TFS500F

5/44




FIG. 5

202290" T19990T




FIG. 6

7/44




FIG. 7




FIG. 8

10055511.062702
20/250 T5500T

8/44




FIG. 9




FIG. 10

1005511.062702

9/44




FIG. 11






FIG. 12


10055511.062702
20/2290 TT555001

10/44



10/055,511, 06/27/02

11/44



202290" FIG. 15




FIG. 16




FIG. 17




FIG. 18

20/230" 11/25/001

13/44




FIG. 19

204290" TFS900T

14/44




FIG. 20

15/44




FIG. 21A




FIG. 21B




FIG. 22

10055511.062702

16/44




FIG. 23

20/290" T. 59500T

17/44






FIG. 24

2042301 11559001

18/44






FIG. 27




FIG. 28

20/44




FIG. 29

20/44




FIG. 30




FIG. 31

21/44

22/44




FIG. 32










FIG. 33

202290" TFS900T

23/44




24/44



10055511.062703

25/44



26/44




FIG. 40

202290" TFS500T

27/44




FIG. 41

10/055,511

28/44




FIG. 42





FIG. 43

FIG. 43

30/44



“30/44” T59900T

31/44




FIG. 45




FIG. 46

1005511-062709

32/44




FIG. 47A




FIG. 47B




FIG. 47C

33/44




FIG. 48

202230 T. 525007

34/44




FIG. 49A




FIG. 49B




FIG. 49C




FIG. 49D

20250715 15:50:20

35/44




FIG. 50A




FIG. 50B




FIG. 50C






FIG. 50D

36/44



100554.069.001

37/44




FIG. 52

1005511.062703

38/44




FIG. 53

10055511.062702

39/44




FIG. 54

10055511.06309

40/44




FIG. 55

1055511-062703
20220715500T

41/44




FIG. 56

202207195001

42/44




FIG. 57A




FIG. 57B




FIG. 58A




FIG. 58B

20220101-032702

43/44




FIG. 59A




FIG. 59B




FIG. 59C

1005511-062002

44/44




FIG. 60A




FIG. 60B

10055511 0320 155007